

EPROM PROGRAMMER PROJECT

Due to a hitch at the printers the main constructional diagram for this project, on page 21 of this issue, has unfortunately been printed incorrectly with essential information missing. The complete, and correct, version of this is reproduced in enlarged form below. Our thanks to the printers for speedily reprinting this diagram.

